

8/027/0086  
cc Tom 0002

**SURFACE INSPECTION  
COMPLIANCE REPORT**

Date of Inspection: October 06, 2009

Case Serial Number: UTU-078278

Operator: Levin Stone

Project Description: Quarry

Legal Description: Section 3, 4, T. 18 S., R. 13 W.

Field Office: Fillmore

Inspector: Jerry Mansfield

---

The quarry for this site has been reclaimed. Levin Stone set up a pallet and stone holding site. They were told that they would need a ROW for the site. They started the application for the ROW but failed to complete as required. Their bond company has notified the USO that the bond is being terminated. A reclamation estimate has been calculated and a notice of bond forfeiture will be sent. The reclamation looks satisfactory and a letter allowing release of the bond has been sent. Tom Munson of UDOGM has asked for an inspection report and photos of the site in order to concur with the release.

/s/Jerry Mansfield  
Signature of Inspector

**RECEIVED E-Mail**  
**OCT 08 2009**  
**Div. of Oil, Gas & Mining**

0002



RECEIVED E-Mail

OCT 9 8 2009

Div. of Oil, Gas & Mining



RECEIVED E-Mail

OCT 08 2009

Dir. of Oil, Gas & Mining





RECEIVED E-Mail

OCT 08 2009

Div. of Oil, Gas & Mining





RECEIVED E-Mail

OCT 08 2009

Div. of Oil, Gas & Mining

